


# Edge analysis

OD

ID




# Surface Inspection with filter

Machine  
parameter

Inspection  
parameter

Cross section  
radial

Cross section  
circumferential



Save data

Read data  
review

View setting

Filter setting

Set color


Data mane

Save screen

# Roughness Inspection –Ra/RMS

Surface view 0 to 360 deg

Line Profile



ID


MD

OD


Line Profile  
with filter

Roughness /Line

# Surface Inspection with filter




# Surface Inspection with filter slope mode






# Example Inspection result 1






Polish mark




Texture mark

# Example Inspection result 2



# Example Inspection result 3



# Example Inspection result 4

